


This small 30 HR long case movement with Alarm was made by Evill & Sons of Bath in circa 1785. The movement was in good order apart from 2 pivots that needed bushing and a polishing of the pallet faces.


The main problem was that of the dial, the black shellac wax was missing from several parts and one of the dial pillars had been forced by a previous repairer which had bent the dial plate around the pillar fixing. This damage was planished out of the plate and the dial was re-waxed, silvered and lacquered.



Damage to dial plate and wax missing from the engraving



The dial after repair



The Evill movement after repair & cleaning